

RCC Panel 6 Foam Impact Test Results (Preliminary)



RCC Panel 6 Impact Test Results


- 5 1/2" long through-thickness crack
- Located on the lock side approximately 6" below the stagnation line (apex)
- Transverses the entire rib width, extends through the lock side channel and onto the panel lower face
- Approximately 3/4" crack on the lower face



- Projectile ink streaks start on RCC panel 6, continue across T-Seal 6 and onto the fiberglass panel 7.
- Foam debris was caught between RCC panel 6 and T-Seal 6.

The CAIB has drawn no conclusions from this test


RCC Panel 6 Impact Test Results



- Visible crack in panel rib, ~ 5" in length emanating from the surface; crack also found in adjacent T-Seal
- Visible as a 3/4" surface crack, ~4" below the apex of the panel
- Easily detectable with routine inspection techniques
- Panel 6 has been removed and will be inspected using a variety of inspection techniques to further characterize the crack

The CAIB has drawn no conclusions from this test

RCC Panel 6 Impact Test Results



The CAIB has drawn no conclusions from this test

T-Seal Crack Adjacent to Panel 6 Rib Crack

- The T-Seal crack is approximately 6" below the stagnation (near the panel crack)
- Approximately 2 1/2" through crack on the RCC T-Seal 6 lower outboard rib
- Crack starts at rib and continues into filets







The CAIB has drawn no conclusions from this test